

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD,
13-BELA,
3-

Liriodendron
502 West Gordon Street
Bel Air
Harford County
Maryland

HABS No. MD-327

Documentation: 11 sheets (1980, including site plan; plan and elevation of
corn crib; and plans, elevations, sections and
construction details of barn)

34 exterior photos (1980)

17 interior photos (1980)

1 set of field records (11 notebooks, 135 photos)

Walter Smalling, Jr., Photographer January, 1980

Main House and Outbuildings

MD-327-1 SOUTHWEST FRONT

MD-327-2 SOUTHWEST FRONT FROM SOUTH

MD-327-3 SOUTHEAST AND NORTHEAST SIDES, GENERAL VIEW

MD-327-4 SOUTHEAST AND NORTHEAST SIDES

MD-327-5 DETAIL OF FRONT DOOR

MD-327-6 DETAIL OF URN, FRONT PORCH

MD-327-7 DETAIL OF TRELLISES AND URNS, FRONT PORCH

MD-327-8 DETAIL OF PORCH, SOUTHEAST END, LOOKING SOUTHWEST

MD-327-9 BRICK 1835 FARMHOUSE, NORTHWEST FRONT

MD-327-10 BRICK 1835 FARMHOUSE, SOUTHWEST AND SOUTHEAST SIDES

MD-327-11 FRAME FARMHOUSE, WEST SIDE AND SOUTH FRONT

MD-327-12 FRAME FARMHOUSE, WEST SIDE

MD-327-13 CORN CRIB, SOUTHEAST FRONT AND NORTHEAST SIDE